

VEHICLE INSPECTION REPORT

PE17HRU

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/03/2017

Year 2017

Mileage 1,633,848 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G150233

Body Style Tractor Unit

MOT Due 31/05/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

COLLECTED AS NON-RUNNER, CORROSION

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4


Features

- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Cracked
Replace

4: Bumper Front
Dented
With Paint Damage



5: Bumper Front Moulding
Broken
Replace

6: Door Mirror Assy nsf
Broken
Replace



7: Panel Rear
Dented
Over 30mm

8: Door osf
Scratched
Over 25mm Thru Paint



9: Door Pad osf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		