

# VEHICLE INSPECTION REPORT

**WF18UZV**

## Nissan Navara TEKNA 2.3 DCI 190PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 30/04/2018

Year 2018

Mileage 113,291 Miles Not Warranted

Fuel Type Diesel

Colour GREY

VIN VSKCTND23U0092577

Body Style Pickup Double Cab

Keys 2

MOT Due 23/05/2026

CAP Clean £8,375.00

CAP Average £7,200.00

CAP Below £5,625.00

Gearbox MANUAL

Gears 6

Axle Combi 4x4

E/MIRRORS, KEYLESS IGNITION

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features


- Heated front seat
- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Screen Front  
Chipped  
Over 10mm

2: Bumper Front  
Chipped  
Multiple Chips



3: Wing nsf  
Dented  
With Paint Damage

4: Bumper Front  
Insecure  
Action Required



5: Qtr Panel nsr  
Chipped  
Multiple Chips

6: Lamp nsr  
Broken  
Replace



7: Boot Lid  
Scratched  
Over 25mm Thru Paint

8: Boot Lid  
Scratched  
Over 25mm Thru Paint



9: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



10: Door osf  
Chipped  
Edge Chip



11: Wing osf  
Chipped  
1 To 5

12: Seat Base Cover osf  
Scuffed  
Over 25mm

## Interior

| Carpet Condition         |    | Average | Upholstery Condition                           |    | Average |
|--------------------------|----|---------|------------------------------------------------|----|---------|
| Seat Condition           |    | Average | Odour                                          |    | No      |
| Engine Runs              | OK |         | Gearbox 1st and Reverse Test                   | OK |         |
| Brakes                   | OK |         | Clutch Slip Test from Static                   | OK |         |
| Parking Brake            | OK |         | Gearbox Static Gear Selection (engine running) | OK |         |
|                          |    |         | No Excessive Smoking                           | OK |         |
| EML light illuminated    | OK |         | Oil warning light illuminated                  | OK |         |
| Airbag light illuminated | OK |         | DPF light illuminated                          | OK |         |
| ABS light illuminated    | OK |         | Service indicator light illuminated            | OK |         |